

Site Summit Historic District





Target Ranging Radar

AHRS Site Number ANC-795

Date of Construction: 1962

Function: Target Ranging

Building Materials: Metal, Fiberglass, Corrugated Aluminum Siding

Building Status: Good

Proposed Action: Retain



Vehicle Garage Foundation

AHRS Site Number ANC-797

Date of Construction: 1959

Function: Vehicle Maintenance

Building Materials: Concrete

Building Status: Poor (modern structures built on foundation)

Proposed Action: Retain

Other: Building Removed Between 1981 and 1995



Electrical Substation C

AHRS Site Number ANC-796

Date of Construction: 1959

Function: Electrical System

Building Materials: Metal, Corrugated Aluminum Siding

Building Status: Fair

Proposed Action: Retain



Helicopter pad

No AHRS Site Number

Date of Construction: 1959

Function: Landing Pad

Building Materials: Cleared Ground, Gravel

Building Status: Good

Proposed Action: Retain



Connector Road

No AHRS Site Number

Date of Construction: 1959

Function: Vehicle Transportation Path

Building Materials: Gravel, Metal Railing

Building Status: Good

Proposed Action: Retain



Radar Test Set Group

No AHRS Site Number

Date of Construction: 1959

Function: Calibrate the Tracking Radars

Building Materials: Mounded Earth, Wood Embedded in Concrete Base

Building Status: Good (electronics were removed)

Proposed Action: Retain



High Power Acquisition Radar (HIPAR) Foundation
(A.K.A. HIPAR Tower Site)

AHRS Site Number ANC-798

Date of Construction: 1962

Function: Radar Facility

Building Materials: Concrete

Building Status: Good (tower and electronics were removed)

Proposed Action: Retain



HIPAR Building

AHRS Site Number ANC-799

Date of Construction: 1962

Function: Radar Facility

Building Materials: Reinforced Concrete

Building Status: Good

Proposed Action: Retain



Sewage Treatment Building

No AHRS Site Number

Date of Construction: 1959

Function: Waste Treatment

Building Materials: Concrete

Building Status: Good

Proposed Action: Demolish

Other: Not Part of the Original Nomination





Battery Building

AHRS Site Number ANC-792

Date of Construction: 1959

Function: Administration, Barracks, Tracking

Building Materials: Metal, Cement Asbestos Board Panel Siding,
Concrete, Aluminum

Building Status: Poor (roof failure, excessive water)

Proposed Action: Demolish



Target Tracking Radar

AHRS Site Number ANC-793

Date of Construction: 1959

Function: Tracking Radar

Building Materials: Metal, Fiberglass

Building Status: Fair

Proposed Action: Demolish



Missile Tracking Radar

AHRS Site Number ANC-794

Date of Construction: 1959

Function: Radar

Building Materials: Metal, Fiberglass

Building Status: Fair

Proposed Action: Demolish





Missile Launch and Storage Building #1 (B)

AHRS Site Number ANC-810

Date of Construction: 1959

Function: Launch Facility

Building Materials: Poured Reinforced Concrete, Tilt-up Concrete
Panels, Metal

Building Status: Fair (excessive graffiti)

Proposed Action: Retain

Missile Launch and Storage Building #2 (A)

AHRS Site Number ANC-814

Date of Construction: 1959

Function: Launch Facility

Building Materials: Poured Reinforced Concrete, Tilt-up Concrete
Panels, Metal

Building Status: Fair (excessive graffiti)

Proposed Action: Retain



Guided Missile Magazine

AHRS Site Number ANC-801

Date of Construction: 1959

Function: Storage

Building Materials: Poured Reinforced Concrete, Earthen Fill, Metal

Building Status: Good

Proposed Action: Retain

High Explosive Magazine

AHRS Site Number ANC-800

Date of Construction: 1959

Function: Storage

Building Materials: Poured Reinforced Concrete, Earthen Fill, Metal

Building Status: Good

Proposed Action: Retain



Fuse and Detonator Magazine

AHRS Site Number ANC-813

Date of Construction: 1959

Function: Storage for Missile Materials

Building Materials: Concrete, Metal

Building Status: Fair

Proposed Action: Retain



Electrical Substation B

AHRS Site Number ANC-808

Date of Construction: 1959

Function: Electrical System

Building Materials: Metal, Corrugated Aluminum Siding

Building Status: Fair

Proposed Action: Retain



Guided Missile Maintenance Facility

AHRS Site Number ANC-804

Date of Construction: 1959

Function: Maintenance

Building Materials: Concrete, Corrugated Metal

Building Status: Fair

Proposed Action: Demolish



Electrical Substation D

AHRS Site Number ANC-811

Date of Construction: 1959

Function: Electrical System

Building Materials: Metal, Corrugated Aluminum Siding

Building Status: Fair

Proposed Action: Demolish



Sentry Station

AHRS Site Number ANC-806

Date of Construction: 1959

Function: Security

Building Materials: Wood Frame, Plywood

Building Status: Fair

Proposed Action: Demolish



Sentry Station

AHRS Site Number ANC-802


Date of Construction: 1959

Function: Security

Building Materials: Wood

Building Status: Fair

Proposed Action: Demolish



Sentry Station

AHRS Site Number ANC-803

Date of Construction: 1959

Function: Security

Building Materials: Wood Frame, Plywood

Building Status: Fair

Proposed Action: Demolish



Vehicle Maintenance Building

AHRS Site Number ANC-805

Date of Construction: 1959

Function: Maintenance

Building Materials: Cement Asbestos Panels, Wood Battens, Poured
Concrete, Wood Frame

Building Status: Fair

Proposed Action: Demolish



Launch Control Building

AHRS Site Number ANC-807

Date of Construction: 1959

Function: Launch Facility

Building Materials: Metal, Reinforce Concrete, Concrete Block, Wood
Frame, Plywood

Building Status: Poor (excessive water)

Proposed Action: Demolish



Water Pump House

No AHRS Site Number

Date of Construction: 1959

Function: Water Transportation

Building Materials: Metal, Wood, Asbestos Board

Building Status: Fair

Proposed Action: Demolish

Other: Not Part of Original Nomination

No Photograph

Electrical Substation (second D)

AHRS Site Number ANC-812

Date of Construction: 1959

Function: Security

Building Materials: Metal, Corrugated Siding

Building Status: Fair

Proposed Action: Demolish

Dog Kennels

AHRS Site Number ANC-809

Date of Construction: 1959

Function: Security

Building Materials: Wood, Metal

Building Status: Fair

Proposed Action: Demolish

Missile Warhead Magazine

AHRS Site Number ANC-815

Date of Construction: 1959

Function: Security

Building Materials: Concrete, Metal

Building Status: Good

Proposed Action: Retain